REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	3/24/2017	**Time:**	8:58 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL				**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58					
City:	Elnora	**Zip:**	47529		**County Number:**	14
VIN:	4UZAAXBV62CJ97773		**License Number:**	D784792	**Bus Number:**	16
Make of Body:	Freightliner	**Year:** 2001	**Make of Chassis:**	Freightliner	**Year:**	2002
Bus Type:	C		**Mileage:**	155003		
Inspection Status:	R	**Inspected By:**	Mike Adams		**PE:**	7407

Violations - Rejected

Inspection Code	Description
82-1-2	See Notes: Any defect inspector deems a violation not listed
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.