

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	3/24/2017	Time:	9:36 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	Zip:	47529	County Number:	14
VIN:	4DRBRABP13A955902	License Number:	B208E	Bus Number:	6
Make of Body:	IC Corporation	Year:	2002	Make of Chassis:	IC Corporation
Year:				Year:	2003
Bus Type:	C	Mileage:	122633		
Inspection Status:	R	Inspected By:	Mike Adams	PE:	7407

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.