REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 3/24/2017 **Time:** 9:36 AM **Name of School Corporation:** NORTH DAVIESS CO. COMM. SCHOOL **Corp ID:** 141375

Address of School Corporation: 5494 E SR 58

City:ElnoraZip:47529County Number:14VIN:4DRBRABP13A955902License Number:Bus Number:6Make of Body:IC Corporation Year:Make of Chassis:IC Corporation Year:2003

Bus Type: C Mileage: 122633

Inspection Status: R Inspected By: Mike Adams PE: 7407

Violations - Rejected

Inspection Code Description

23-1-3 Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.