

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual      **Date:** 3/24/2017      **Time:** 10:39 AM  
**Name of School Corporation:** THE PLAYSCHOOL DAYCARE (29)      **Corp ID:** 290030  
**Address of School Corporation:** 11501 E 116th St.  
**City:** Fishers      **Zip:** 46037      **County Number:** 29  
**VIN:** 1GB0G2BF2F1247536      **License Number:** TK208NAY      **Bus Number:** 10  
**Make of Body:** Chevrolet      **Year:** 2015      **Make of Chassis:** Chevrolet      **Year:** 2015  
**Bus Type:** A1      **Mileage:** 8446  
**Inspection Status:** R      **Inspected By:** Chris Kath      **PE:** 6690

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
8-1-4	See Notes: Any defect inspector deems a violation not listed
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.