

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection                      **Date:** 3/24/2017                      **Time:** 10:37 AM  
**Name of School Corporation:** CENTERVILLE-ABINGTON COMM SCHS                      **Corp ID:** 898360  
**Address of School Corporation:** 116 W SOUTH ST  
**City:** CENTERVILLE   **Zip:** 47330                      **County Number:** 89  
**VIN:** 1HVBBABN6YH290835                      **License Number:** 17297                      **Bus Number:** M5  
**Make of Body:** Carpenter   **Year:** 2000                      **Make of Chassis:** IC Corporation   **Year:** 2000  
**Bus Type:** B                      **Mileage:** 62357  
**Inspection Status:** R                      **Inspected By:** Jeremy Mason                      **PE:** 8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
29-1-1	The flooring is improper
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

### Violations - Out of Service

Inspection Code   Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**