

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 3/24/2017 **Time:** 10:53 PM
Name of School Corporation: BLUE RIVER VALLEY SCHOOLS **Corp ID:** 333405
Address of School Corporation: PO Box 217
City: Mount Summit **Zip:** 47361 **County Number:** 33
VIN: 1UZABRCS88CY45720 **License Number:** 30828 **Bus Number:** 17
Make of Body: Mid Bus, Inc. **Year:** 2006 **Make of Chassis:** Freightliner **Year:** 2006
Bus Type: C **Mileage:** 45797
Inspection Status: O **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-1	There are any loose, broken, or missing mountings
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
20-1-7	If bus manufactured after 5-2-1994, one (1) inch reflective tape is not applied to the door outline, is missing, or badly faded (two (2) is permissible on bumper below door if insufficient space on body)
11-1-3	Bumpers are not black

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.