

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 3/24/2017      **Time:** 10:53 PM  
**Name of School Corporation:** BLUE RIVER VALLEY SCHOOLS      **Corp ID:** 333405  
**Address of School Corporation:** PO Box 217  
**City:** Mount Summit      **Zip:** 47361      **County Number:** 33  
**VIN:** 1UZABRCS88CY45720      **License Number:** 30828      **Bus Number:** 17  
**Make of Body:** Mid Bus, Inc.      **Year:** 2006      **Make of Chassis:** Freightliner      **Year:** 2006  
**Bus Type:** C      **Mileage:** 45797  
**Inspection Status:** O      **Inspected By:** Jeremy Mason      **PE:** 8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-7	If bus manufactured after 5-2-1994, one (1) inch reflective tape is not applied to the door outline, is missing, or badly faded (two (2) is permissible on bumper below door if insufficient space on body)
11-1-3	Bumpers are not black
52-1-1	There are any loose, broken, or missing mountings
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**