REPORT OF SCHOOL BUS INSPECTION

Type of Re-Inspection Date: 3/27/2017 **Time**: 9:26 AM Inspection: Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP 131300 Corp ID: **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1GBL7T1C01J509024 B951B **Bus Number:** 22 Number: Make of Blue Bird Chevrolet Year: Year: 2001 2002 Make of Body: Corporation Chassis: **Bus Type:** С Mileage: 196641 Inspected PE: Inspection Status: R Travis Coryea 5892 By:

Violations - Rejected

Inspection Code

Description

25-1-1 Mirror or mirror backs that are loose or improperly mounted

One (1) taillight or one (1) brake light does not function

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.