## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Date: 3/29/2017 Time: 10:30 PM

Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4RDBUSKPXEB405437License Number:55NEWBus Number:55

Make of Body: IC Corporation Year: 2014 Make of Chassis: IC Corporation Year: 2014

Bus Type: C Mileage: 61977

Inspection Status: O Inspected By: Travis Coryea PE: 5892

## **Violations - Rejected**

<u>Inspection</u> <u>Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
2-1-1	Required back-up lights do not function.

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
59-2-6	LED type lights have 50% or more pixels inoperable in one light. (NOTE: one letter in
	the word "STOP" equals one light.)

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.