

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/29/2017	<b>Time:</b> 10:31 PM
<b>Name of School Corporation:</b> CRAWFORD CO. COMM. SCHOOL CORP	<b>Corp ID:</b> 131300	
<b>Address of School Corporation:</b> 5808 E Administration Rd		
<b>City:</b> Marengo	<b>Zip:</b> 47140	<b>County Number:</b> 13
<b>VIN:</b> 1GBJG31K091163308	<b>License Number:</b> 81641	<b>Bus Number:</b> 85
<b>Make of Body:</b> Collins Bus Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2009	<b>Mileage:</b> 77956	<b>Year:</b> 2009
<b>Bus Type:</b>		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Travis Coryea	<b>PE:</b> 5892

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------