# **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Post-Crash Inspectio	n	Date:	3/30/2017	Time:	3:17 PM
Name of Schoo Address of Sch	I Corporation: ool Corporation:		EW CONS. SCHOC Marr Rd	DL CORP.	Corp ID:	30365
City:	Columbus	Zip:	47201		County Number:	3
VIN:	4UZABRDT4FCGK9225		License Number:	8440	Bus Number:	153
Make of Body:	Thomas Built Buses, Inc.	Year: 2014	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2015
Bus Type:	С		Mileage:	47114		
Inspection Status:	0	Inspect By:	<b>ed</b> Travis Coryea		PE:	5892

## **Violations - Rejected**

#### Inspection Code Description

# Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.