

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/31/2017	<b>Time:</b>	9:02 AM
<b>Name of School Corporation:</b>	MEDORA COMMUNITY SCHOOL CORP.			<b>Corp ID:</b>	363640
<b>Address of School Corporation:</b>	Box 248				
<b>City:</b>	Medora	<b>Zip:</b>	47260	<b>County Number:</b>	36
<b>VIN:</b>	1BAKF CPA4BF274979	<b>License Number:</b>	4413	<b>Bus Number:</b>	2
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	72739	<b>Year:</b>	2010
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Travis Coryea	<b>PE:</b>	5892

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.