

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	3/31/2017	Time:	9:39 AM
Name of School Corporation:	MEDORA COMMUNITY SCHOOL CORP.	Corp ID:			363640
Address of School Corporation:	Box 248				
City:	Medora	Zip:	47260	County Number:	36
VIN:	1BAKF CPA4BF274979	License Number:	4413	Bus Number:	2
Make of Body:	Blue Bird Corporation	Year:	2009	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	72739	Year:	2010
Inspection Status:	R	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.