

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/5/2017 Time: 10:30 AM  
Name of School Corporation: PRIMROSE SCHOOL OF CARMEL Corp ID: 290005  
Address of School Corporation: 780 W. Carmel Dr.  
City: Carmel Zip: 46032 County Number: 29  
VIN: 1GBHG31C091111801 License Number: B490C Bus Number: 1  
Make of Body: Chevrolet Year: 2009 Make of Chassis: Chevrolet Year: 2009  
Bus Type: A1 Mileage: 14853  
Inspection Status: O Inspected By: John Pang PE: 6196

### Violations - Rejected

### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.