

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/7/2017 **Time:** 8:27 AM
Name of School Corporation: HANOVER COMM. SCHOOL CORP. **Corp ID:** 454580
Address of School Corporation: PO Box 645
City: Cedar Lake **Zip:** 46303 **County Number:** 45
VIN: 1GB3G2BG1C1196659 **License Number:** 14188 **Bus Number:** 44
Make of Body: Star Trans **Year:** 2012 **Make of Chassis:** Chevrolet **Year:** 2012
Bus Type: **Mileage:** 46434
Inspection Status: R **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description