REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	4/7/2017	**Time:**	8:32 AM
Name of School Corporation:	HANOVER COMM. SCHOOL CORP.				**Corp ID:**	454580
Address of School Corporation:	PO Box 645					
City:	Cedar Lake	**Zip:**	46303		**County Number:**	45
VIN:	1GB3B2BG3C1195996		**License Number:**	14189	**Bus Number:**	43
Make of Body:	Star Trans **Year:**	2012	**Make of Chassis:**	Chevrolet	**Year:**	2012
Bus Type:			**Mileage:**	26149		
Inspection Status:	R	**Inspected By:**	Nathan Sherer		**PE:**	7029

Violations - Rejected

Inspection Code	Description
70-1-7	Any emergency window is too difficult to open

Violations - Out of Service

Inspection Code	Description

Bus Type Description