

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 4/10/2017	Time: 1:11 PM
Name of School Corporation: MACONAQUAH SCHOOL CORPORATION	Corp ID: 525615	
Address of School Corporation: 7932 S Strawtown Pike		
City: Bunker Hill	Zip: 46914	County Number: 52
VIN: 1BABNBKA15F221262	License Number: 7312	Bus Number: 8
Make of Body: Blue Bird Corporation	Year: 2004	Make of Chassis: Blue Bird Corporation
Bus Type: D	Mileage: 149436	Year: 2005
Inspection Status: O	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-2	Rims are bent or loose
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
70-2-3	Any emergency window will not open
63-2-3	Any tire is flat

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.