

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/13/2017	<b>Time:</b>	8:54 AM		
<b>Name of School Corporation:</b>	CRAWFORD CO. COMM. SCHOOL CORP			<b>Corp ID:</b>	131300		
<b>Address of School Corporation:</b>	5808 E Administration Rd						
<b>City:</b>	Marengo	<b>Zip:</b>	47140	<b>County Number:</b>	13		
<b>VIN:</b>	1GBJG31K391164372	<b>License Number:</b>	81640	<b>Bus Number:</b>	86		
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Chevrolet	<b>Year:</b>	2009
<b>Bus Type:</b>			<b>Mileage:</b>	83614			
<b>Inspection Status:</b>	A	<b>Inspected By:</b>	Travis Coryea	<b>PE:</b>	5892		

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description