REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/17/2017	**Time:**	9:45 AM
Name of School Corporation:	A NEW DAWN DAY CARE			**Corp ID:**	1042
Address of School Corporation:	302 Hunterstation Rd				
City:	Sellersburg	**Zip:**	47172	**County Number:**	10
VIN:	1GB0G2BA5D1115517	**License Number:**	B707H	**Bus Number:**	2
Make of Body:	Star Trans **Year:** 2013	**Make of Chassis:**	Star Trans	**Year:**	2013
Bus Type:	A2	**Mileage:**	30985		
Inspection Status:	O	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4” min), 2 40”x40”x56” triangular bandages, 6 3”x3” gauze pads, 4 2”x4.1 yard rolls of gauze, 3 oval eye pads, 1 1”x5 yard of adhesive tape, 1 label instruction.
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code	Description
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**