REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/17/2017 Time: 9:45 AM Name of School Corporation: A NEW DAWN DAY CARE Corp ID: 1042

Address of School Corporation: 302 Hunterstation Rd

City:SellersburgZip:47172County Number:10VIN:1GB0G2BA5D1115517License Number:Bus Number:2Make of Body:Star Trans Year:2013Make of Chassis:Star Trans Year:2013

Bus Type: A2 Mileage: 30985

Inspection Status: O Inspected By: Troy Boyd PE: 5171

Violations - Rejected

Inspection

Code	<u>Description</u>
	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
17-1-1	Any dome light is inoperative

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

8-2-1 There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.