

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	4/17/2017	Time:	3:31 PM
Name of School Corporation:	A NEW DAWN DAY CARE	Corp ID:	1042		
Address of School Corporation:	302 Hunterstation Rd				
City:	Sellersburg	Zip:	47172	County Number:	10
VIN:	1GBHG31V261178901	License Number:	B876F	Bus Number:	1
Make of Body:	Chevrolet	Year:	2006	Make of Chassis:	Chevrolet
Year:	2006	Year:	2006		
Bus Type:	A2	Mileage:	71838		
Inspection Status:	O	Inspected By:	Troy Boyd	PE:	5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**