

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 4/17/2017 **Time:** 3:31 PM
Name of School Corporation: A NEW DAWN DAY CARE **Corp ID:** 1042
Address of School Corporation: 302 Hunterstation Rd
City: Sellersburg **Zip:** 47172 **County Number:** 10
VIN: 1GB0G2BA5D1115517 **License Number:** B707H **Bus Number:** 2
Make of Body: Star Trans **Year:** 2013 **Make of Chassis:** Star Trans **Year:** 2013
Bus Type: A2 **Mileage:** 30985
Inspection Status: O **Inspected By:** Troy Boyd **PE:** 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
17-1-1	Any dome light is inoperative
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**