

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/20/2017	Time:	11:24 AM
Name of School Corporation:	M.S.D. DECATUR TOWNSHIP			Corp ID:	495300
Address of School Corporation:	5251 Kentucky Ave				
City:	Indianapolis	Zip:	46221	County Number:	49
VIN:	4DRBUSKP9BB334114			License Number:	G712329
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation
Bus Type:	C			Year:	2011
Inspection Status:	O	Inspected By:	Alex Willis	PE:	4760

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
67-1-2	Rims are bent or loose

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
55-2-3	Any steering component jams or inhibits safe movement
59-2-5	There are no OOS criteria for the optional school bus crossing arm
63-2-3	Any tire is flat
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.