REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	4/20/2017	**Time:**	11:24 AM
Name of School Corporation:	M.S.D. DECATUR TOWNSHIP			**Corp ID:**	495300
Address of School Corporation:	5251 Kentucky Ave				
City:	Indianapolis	**Zip:**	46221	**County Number:**	49
VIN:	4DRBUSKP9BB334114	**License Number:**	G712329	**Bus Number:**	2001
Make of Body:	IC Corporation **Year:** 2010	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	96028		
Inspection Status:	O	**Inspected By:**	Alex Willis	**PE:**	4760

Violations - Rejected

Inspection Code	Description
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
67-1-2	Rims are bent or loose

Violations - Out of Service

Inspection Code	Description
55-2-3	Any steering component jams or inhibits safe movement
59-2-5	There are no OOS criteria for the optional school bus crossing arm
63-2-3	Any tire is flat
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.