

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/20/2017 **Time:** 9:58 AM
Name of School Corporation: PERU COMMUNITY SCHOOLS **Corp ID:** 525635
Address of School Corporation: 35 W 3rd St
City: Peru **Zip:** 46970 **County Number:** 52
VIN: 1GB6G3AGXA1168294 **License Number:** 83999 **Bus Number:** Tiger2
Make of Body: Starcraft **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: A2 **Mileage:** 63267
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
95-1-10	Does not move smoothly or rest solidly on the ground
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
50-1-2	The seat belt cutter is not secured

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.