## **REPORT OF SCHOOL BUS INSPECTION**

| Type of Inspection:  | Annual          |               | Date:            | 4/20/2017 | Time:                 | 10:44 AM |
|--|-----------------|---------------|------------------|-----------|-----------------------|----------|
| Name of School Corporation: PERU COMMUNITY SCHOOLSCorp ID: |                 |               |                  |           |                       | 525635   |
| Address of School  | Corporation:    | 35 W 3rd St   |                  |           |                       |          |
| City:  | Peru            | Zip:          | 46970            |           | <b>County Number:</b> | 52       |
| VIN:   | 1GB6G2AG7A      | 1167176       | License Number:  | 84000     | Bus Number:           | Tiger1   |
| Make of Body:  | Starcraft Year: | 2009          | Make of Chassis: | Chevrolet | Year:                 | 2010     |
| Bus Type:  | A2              |               | Mileage:         | 48517     |                       |          |
| Inspection Status:   | 0               | Inspected By: | Randy McPike     |           | PE:                   | 7018     |

**Violations - Rejected** 

Inspection Code Description

## **Violations - Out of Service**

Inspection CodeDescription50-2-1There is no seat belt cutter in the vehicle

## Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.

2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.