

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	4/21/2017	Time:	10:17 AM
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635
Address of School Corporation:	35 W 3rd St				
City:	Peru	Zip:	46970	County Number:	52
VIN:	1T7HT4B2X21114572	License Number:	18246	Bus Number:	14
Make of Body:	Thomas Built Buses, Inc.	Year:	2001	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	216781
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.