

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|-----------------------|--------------|------|
| Type of Inspection: | Annual | Date: | 4/25/2017 | Time: | 9:24 AM | | |
| Name of School Corporation: | UNION-NORTH UNITED SCHOOL CORP | | | Corp ID: | 717215 | | |
| Address of School Corporation: | 22601 Tyler Rd | | | | | | |
| City: | Lakeville | Zip: | 46536 | County Number: | 71 | | |
| VIN: | 1HVBBAAN9YH306348 | License Number: | B542H | Bus Number: | 3 | | |
| Make of Body: | Blue Bird Corporation | Year: | 2000 | Make of Chassis: | Blue Bird Corporation | Year: | 2001 |
| Bus Type: | B | Mileage: | 188928 | | | | |
| Inspection Status: | A | Inspected By: | Travis Harrold | PE: | 8022 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.