

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/1/2017	<b>Time:</b> 9:24 AM	
<b>Name of School Corporation:</b> NORTH SPENCER COUNTY SCHOOL CO	<b>Corp ID:</b> 747385		
<b>Address of School Corporation:</b> 3720 E SR 162			
<b>City:</b> Lincoln City	<b>Zip:</b> 47552	<b>County Number:</b> 74	
<b>VIN:</b> 4DRBUSKP8BB254805	<b>License Number:</b> B545F	<b>Bus Number:</b> 12	
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 2011
<b>Bus Type:</b> C	<b>Mileage:</b> 61969		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Kelly Hammond	<b>PE:</b> 6682	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-9	If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-2	LED type lights have 50% or more pixels inoperable in one light

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**