REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	5/3/2017	**Time:**	11:08 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			**Corp ID:**	525625
Address of School Corporation:	PO Box 550				
City:	Converse	**Zip:**	46919	**County Number:**	52
VIN:	1GBJG31UX61211085	**License Number:**	76867	**Bus Number:**	2SAV
Make of Body:	Mid Bus, Inc. **Year:** 2006	**Make of Chassis:**	Mid Bus, Inc.	**Year:**	2006
Bus Type:	A2	**Mileage:**	80938		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
37-1-1	The horn does not operate at all

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**