

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/3/2017	Time: 11:08 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 1GBJG31UX61211085	License Number: 76867	Bus Number: 2SAV
Make of Body: Mid Bus, Inc. Year: 2006	Make of Chassis: Mid Bus, Inc. Year: 2006	
Bus Type: A2	Mileage: 80938	
Inspection Status: O	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
37-1-1	The horn does not operate at all

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**