REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 5/5/2017 Time: 6:16 PM Name of School Corporation: ELWOOD COMMUNITY SCHOOL CORP. Corp ID: 485280

Address of School Corporation: 1306 N Anderson St

City:ElwoodZip:46036County Number:48VIN:4DRBUSKP79B673965License Number:32009Bus Number:3Make of Body:IC Corporation Year:2009Make of Chassis:IC Corporation Year:2009

Bus Type: B Mileage: 74679

Inspection Status:RInspected By: Jeremy MasonPE:8139

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

57-1-5 Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.