## REPORT OF SCHOOL BUS INSPECTION

Address of School Corporation: 1306 N Anderson St

City:ElwoodZip:46036County Number:48VIN:4DRBUSKP79B673965License Number:32009Bus Number:3Make of Body:IC Corporation Year:2009Make of Chassis:IC Corporation Year:2009

Bus Type: B Mileage: 74679

Inspection Status: A Inspected By: Jeremy Mason PE: 8139

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.