REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	5/5/2017	**Time:**	6:16 PM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.			**Corp ID:**	485280
Address of School Corporation:	1306 N Anderson St				
City:	Elwood	**Zip:**	46036	**County Number:**	48
VIN:	4DRBUSKP79B673965	**License Number:**	32009	**Bus Number:**	3
Make of Body:	IC Corporation **Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:**	2009
Bus Type:	B	**Mileage:**	74679		
Inspection Status:	R	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.