

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	5/5/2017	Time:	6:16 PM		
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.			Corp ID:	485280		
Address of School Corporation:	1306 N Anderson St						
City:	Elwood	Zip:	46036	County Number:	48		
VIN:	4DRBUSKP79B673965		License Number:	32009	Bus Number:	3	
Make of Body:	IC Corporation	Year:	2009	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	B			Mileage:	74679		
Inspection Status:	R	Inspected By:	Jeremy Mason	PE:	8139		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.