

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection	Date: 5/5/2017	Time: 6:16 PM	
Name of School Corporation: ELWOOD COMMUNITY SCHOOL CORP.	Corp ID: 485280		
Address of School Corporation: 1306 N Anderson St			
City: Elwood	Zip: 46036	County Number: 48	
VIN: 4DRBUSKP79B673965	License Number: 32009	Bus Number: 3	
Make of Body: IC Corporation	Year: 2009	Make of Chassis: IC Corporation	Year: 2009
Bus Type: B	Mileage: 74679		
Inspection Status: R	Inspected By: Jeremy Mason	PE: 8139	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.