REPORT OF SCHOOL BUS INSPECTION

Type of 10:36 5/17/2017 **Time**: Annual Date: Inspection: AM Name of School Corporation: **ELKHART COMMUNITY SCHOOLS** 202305 Corp ID: **Address of School Corporation:** 2720 California Rd County City: Elkhart Zip: 46514 20 Number: License VIN: 7 4UZAAXCS57CW43309 1847 **Bus Number:** Number: Make of Thomas Built Buses, Year: 2005 Freightliner Year: Make of Body: 2007 Inc. Chassis: **Bus Type:** С Mileage: 102525 Inspection Inspected

By:

Wes Rowlader

PE:

7427

Violations - Rejected

Status:

Inspection Code Description

23-1-5 Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code Description

0

50-2-1 There is no seat belt cutter in the vehicle

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.