

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/19/2017	Time:	7:31 AM		
Name of School Corporation:	FRANKTON-LAPEL COMM. SCHLS.			Corp ID:	485245		
Address of School Corporation:	7916 W 300 N						
City:	Anderson	Zip:	46011	County Number:	48		
VIN:	4DRBUSKP4BB344422		License Number:	74819	Bus Number:	28	
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	C			Mileage:	56789		
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139		

### Violations - Rejected

### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.