

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 5/19/2017 **Time:** 1:18 PM
Name of School Corporation: NEW CASTLE COMM. SCHOOL CORP. **Corp ID:** 333445
Address of School Corporation: 236 W CR 100 S
City: New Castle **Zip:** 47362 **County Number:** 33
VIN: 4DRBWAAR3CB462812 **License Number:** 373 **Bus Number:** 2
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2011
Bus Type: D **Mileage:** 54134
Inspection Status: O **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
3-2-1	Battery will not activate the starting motor

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.