

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/19/2017	Time:	1:18 PM		
Name of School Corporation:	NEW CASTLE COMM. SCHOOL CORP.			Corp ID:	333445		
Address of School Corporation:	236 W CR 100 S						
City:	New Castle	Zip:	47362	County Number:	33		
VIN:	4DRBWAAR3CB462812		License Number:	373	Bus Number:	2	
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	D			Mileage:	54134		
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
3-2-1	Battery will not activate the starting motor

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.