REPORT OF SCHOOL BUS INSPECTION

Type of 10:10 5/22/2017 **Time**: Annual Date: Inspection: AM Name of School Corporation: ATTICA CONSOLIDATED SCH. CORP. 232435 Corp ID: **Address of School Corporation:** 205 College St County City: Attica Zip: 47918 23 Number: License VIN: 1GB3G3BG5B1153706 12855 **Bus Number:** 15 Number: Make of Blue Bird Chevrolet Year: **Year:** 2011 Make of Body: 2011 Corporation Chassis: **Bus Type:** D Mileage: 54649 Inspected PE: **Inspection Status:** R Nate King 7421 By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.