# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 5/31/2017 | **Time:** | 8:52 AM |
| **Name of School Corporation:** | YORKTOWN COMMUNITY SCHOOLS | | | **Corp ID:** | 181910 |
| **Address of School Corporation:** | 8800 W Smith St | | | | |
| **City:** | Yorktown | **Zip:** | 47396 | **County Number:** | 18 |
| **VIN:** | 1GBJG31K981207255 | **License Number:** | 73873 | **Bus Number:** | 101 |
| **Make of Body:** | Chevrolet **Year:** 2008 | **Make of Chassis:** | Chevrolet | **Year:** | 2008 |
| **Bus Type:** | A1 | **Mileage:** | 56230 | | |
| **Inspection Status:** | O | **Inspected By:** | Jamie Hotchkiss | **PE:** | 6458 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 64-2-1 | Any rear turn signal does not function properly |

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**