

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/8/2017	Time: 10:19 AM
Name of School Corporation: SOUTH HARRISON COMM. SCH. CORP	Corp ID: 313190	
Address of School Corporation: 315 S Harrison Dr		
City: Corydon	Zip: 47112	County Number: 31
VIN: 4UZAAXCT24CL83486	License Number: E714871	Bus Number: 26
Make of Body: Freightliner	Year: 2004	Make of Chassis: Freightliner
Bus Type: C	Mileage: 128018	Year: 2004
Inspection Status: O	Inspected By: Troy Boyd	PE: 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated
24-1-1	The bus body has rust or rusted through areas which may weaken the body

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.