## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	6/8/2017	Time:	10:19 AM
Name of School Co	orporation: SOU	TH HARRISON	COMM. SCH. COR	Р	Corp ID:	313190
Address of School	Corporation:	315 S Harrison	Dr			
City:	Corydon	Zip:	47112		<b>County Number:</b>	31
VIN:	4UZAAXCT24CL	83486	License Number:	E714871	Bus Number:	26
Make of Body:	Freightliner Year:	2004	Make of Chassis:	Freightliner	Year:	2004
Bus Type:	С		Mileage:	128018		
Inspection Status:	0	Inspected By:	Troy Boyd		PE:	5171

## **Violations - Rejected**

Inspection Code	<u>Description</u>
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated
24-1-1	The bus body has rust or rusted through areas which may weaken the body

## Violations - Out of Service

<u>Inspection</u> <u>Code</u>	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.