REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/8/2017	**Time:**	10:19 AM
Name of School Corporation:	SOUTH HARRISON COMM. SCH. CORP			**Corp ID:**	313190
Address of School Corporation:	315 S Harrison Dr				
City:	Corydon	**Zip:**	47112	**County Number:**	31
VIN:	4UZAAXCT24CL83486	**License Number:**	E714871	**Bus Number:**	26
Make of Body:	Freightliner **Year:** 2004	**Make of Chassis:**	Freightliner	**Year:**	2004
Bus Type:	C	**Mileage:**	128018		
Inspection Status:	O	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated
24-1-1	The bus body has rust or rusted through areas which may weaken the body

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.