

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/8/2017 Time: 10:19 AM  
Name of School Corporation: SOUTH HARRISON COMM. SCH. CORP Corp ID: 313190  
Address of School Corporation: 315 S Harrison Dr  
City: Corydon Zip: 47112 County Number: 31  
VIN: 4UZAAXCT24CL83486 License Number: E714871 Bus Number: 26  
Make of Body: Freightliner Year: 2004 Make of Chassis: Freightliner Year: 2004  
Bus Type: C Mileage: 128018  
Inspection Status: O Inspected By: Troy Boyd PE: 5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated
24-1-1	The bus body has rust or rusted through areas which may weaken the body

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.