REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:6/13/2017Time:9:08 AMName of School Corporation:CULVER COMMUNITY SCHOOLS CORP.Corp ID:505455

Address of School Corporation: PO Box 231

City:CulverZip:46511County Number:50VIN:4DRBUSKP0DB255398License Number:11746Bus Number:15Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2013

Bus Type: C Mileage: 79910

Inspection Status: R Inspected By: Travis Harrold PE: 8022

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

Washers do not function properly in any manner

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.