## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Date: 6/29/2017 Time: 10:18 AM

Name of School
Corporation:

SCHOOL CITY OF HOBART SERVICE CTR
Corp ID: 454730

Address of School Corporation: 200 S Hobart Rd

City: Hobart Zip: 46342 County 45 Number:

Make of Body: Chevrolet Year: 2011 Make of Collins Bus Chassis: Corporation Year: 2011

Bus Type: B Mileage: 87609

Inspection Status: R Inspected By: Tim Grayson PE: 7558

## **Violations - Rejected**

## Inspection Code Description

16-1-1 There are any leaks from the differential, pinion seal, or either rear wheel seal

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.