## REPORT OF SCHOOL BUS INSPECTION

Type of Time: Annual Date: 7/7/2017 10:39 AM Inspection:

Name of School Corporation: BAUGO COMMUNITY SCHOOLS Corp ID: 202260

**Address of School Corporation:** 29125 CR 22 W

City: Elkhart Zip: 46517 County Number: 20 VIN: 4DRBUAFP56B240712 License Number: 11 Bus Number: 11

IC Make of Body: Year: 2006 Make of Chassis: IC Corporation Year: 2006 Corporation

**Bus Type:** Mileage: 128888

Inspection Status: R Inspected By: Wes Rowlader PE: 7427

## **Violations - Rejected**

## **Inspection Code** Description LED type lights have 25% or more of the pixels inoperable in any one light 2-1-4

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.