REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 7/12/2017 Time: 10:35 AM

Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

 City:
 Flora
 Zip:
 46929
 County Number:
 8

 VIN:
 4DRBUC8P8GB121465
 License Number:
 10247
 Bus Number:
 14

Make of Body: IC Corporation Year: 2016 Make of Chassis: IC Corporation Year: 2016

Bus Type: C Mileage: 20366

Inspection Status: O Inspected By: Nate King PE: 7421

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

59-2-4 Stop arm does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.